



Independent
Specialists
in Land Rover
Jaguar & Ineos

9F Centurion Court, Leyland
Lancashire, PR25 3UQ

Tel: 01772 368807

Whatsapp: 07857 157684

Email: service@kmotors.co.uk

Job Report

VAT Reg: 323 1807 87

Company Reg: 5141832

Manufacturer: LAND ROVER
Model: Range Rover Sport 2 (L494)
Engine Size: 2993
Fuel: DIESEL
Repair Category: Engine - Turbo

Description:

DISCONNECT ELECTRICAL CONNECTORS TO BODY AND MAP SENSOR, LOOSEN INLET AND OUTLET HOSE CLAMPS, REMOVE C-CIP AND OFF INLET COVER TO REMOVE THROTTLE BODY.

REPLACE THROTTLE BODY, CLEAR DTCS AND TEST DRIVE. POSSIBILITY OF EXTRA LABOUR IF DPF REGEN REQUIRED.

Part Number	Description	Unit Price	Qty	Total (Ex VAT)
LR078546	REFUNDABLE SURCHARGE	£72.45	1	£72.45
LR078546	THROTTLE BODY AND MOTOR	£390.63	1	£390.63
ZLABOUR	LABOUR CHARGE	£74.50	1	£74.50

Notes:

Total (Exc VAT): £537.58

VAT: £107.52

Total (Inc VAT): £645.10

Extra costs incurred will always be notified in advance. E and O.E.