



**Independent
Specialists
in Land Rover
Jaguar & Ineos**

9F Centurion Court, Leyland
Lancashire, PR25 3UQ
Tel: 01772 368807
Whatsapp: 07857 157684
Email: service@kmotors.co.uk

Job Report

VAT Reg: 323 1807 87
Company Reg: 5141832

Manufacturer: LAND ROVER
Model: Range Rover Sport 2 (L494)
Engine Size: 2993
Fuel: DIESEL
Repair Category: Electrical - Body

Description:

REMOVE REAR SEAT AND ATTACHED LEATHER TRIM,
REPLACE DAMAGED WIRE TO SRS CONNECTOR WITH
LAND ROVER EXTERIOR OVERLAY.
RECONNECT SEAT AND RUN DIAGNOSTICS TO
CONFIRM SUCCESSFUL REPAIR.

Part Number	Description	Unit Price	Qty	Total (Ex VAT)
LR110737	WIRING - REPAIR	£4.18	1	£4.18
ZLABOUR	LABOUR CHARGE	£74.50	3	£223.50

Notes:

Total (Exc VAT): £227.68
VAT: £45.54
Total (Inc VAT): £273.22

Extra costs incurred will always be notified in advance. E and O.E.